

Fig. 4






Fig. 6

STRTING CURRENT PATTERN	STARTING CURRENT	U PHASE LINE 9a	V PHASE LINE 9b	W PHASE LINE 9c
PATTERN 1	V→U	GND	V _{CC}	NC
PATTERN 2	V→W	NC	V _{CC}	GND
PATTERN 3	U→W	V _{CC}	NC	GND
PATTERN 4	U→V	V _{CC}	GND	NC
PATTERN 5	W→V	NC	GND	V _{CC}
PATTERN 6	W→U	GND	NC	V _{CC}